

2.9. Report on Monitoring of Construction Practices of Confined Masonry Structure in Indonesia
(Keiko SAKODA)

インドネシアの枠組み組積造建設モニタリング結果の概要と課題 (迫田恵子)



**Monitoring activity report
on
housing reconstruction
in Yogyakarta, Indonesia**

12.Mar.2008

NPO EVAA
(Ex-volunteers association for Architects)
Keiko Sakoda

1. Brief introduction
of Central Java Earthquake in 2006
2. Progress and achievement
of its reconstruction period for housing quality improvement
3. Issues in the field
(Technical aspect and Structural aspect)
4. Way forward

Character of the Damage

Location	Central Java, Indonesia	Kobe, Japan
Date & Time	27.May. 2007 A.M. 5:53	17.Jan.1995 A.M. 5:45
Magnitude	6.3	7.3
Dead	5,479	6,434
Injured	38,588	43,792
Damaged House	579,000	249,180

Source: Kimio TAKEYA, JICA Central Java Earthquake Reconstruction Program Advisor (2006)
"Central Java Earthquake Disaster, And Japanese Support "Executive Summary"

→ Heavily damage for "residential houses"


Reason

Its Poor Construction

- ● Lack of engineering theory
- ● Inadequate size of structural parts
- ● Poor quality of materials
- ● Inappropriate installation
- ● Unskilled labors



"Man-made"
failure

Typical type of house in Indonesia



Brick house

- Unreinforced Masonry
(Majority in pre-quake period)
- Confined Masonry
(Majority in post-quake period)



Housing Quality Improvement through housing reconstruction period

Information to build safer house

Prototype Drawings




Compared to pre-earthquake period,

- URM to CM
- Better materials
- Better mixture (Mortar, Concrete)
- More firmed joint parts
- Stronger foundation

Field condition




From field survey with 102 sampling (6 samples × 17 districts), 3 major structural problems could be found as follows.
76.5% of total samples had one or more problems of those.

Exposed iron bars 30.39% (31)	Main structure parts with inadequate dimension 26.47% (27)	Not compacted concrete 30.39% (31)
----------------------------------	---	---------------------------------------

Source: Field survey

Issue - Technical difficulty



- Assembling many iron bars (Max 12) in small dimension
- Bending or arranging iron bars with bigger dimension
- Concrete filling in small dimension parts because of bigger dimension's iron bar



Source: Field interview with construction workers

Issues - Structural topic

Confined Masonry

A. "Flame first" ① Concrete structure ② Brick wall	B. "Wall first" ① Brick wall ② Concrete structure
---	--

A. Flame first	B. Wall first
	
<p>Partly brick wall first and concrete structure next. But this require complicated form work.</p> <ul style="list-style-type: none"> ● Merits: <ul style="list-style-type: none"> -Easy to secure appropriate dimension of structure members ● Demerits: <ul style="list-style-type: none"> -Less confined effects, -Needs many form panels, -Complicated form work (need to cut panels → difficult to reuse) 	<p>In Indonesia, it's widely common to sandwich opening spaces of brick walls with 2 form panels (No spacer).</p> <ul style="list-style-type: none"> ● Merits: <ul style="list-style-type: none"> -Higher confined effects -Easy form work and less form panels ● Demerits: <ul style="list-style-type: none"> -Difficult to secure the adequate dimension of structure parts

Issues in the field = {

Technical difficulties
 +
Structural issues

→ Both kinds of issues are related to **installment of material/structural parts** (Not material quality only).

In non-engineered site, **workers' skill levels vary** a lot.
 → Need to disseminate **workers-friendly construction methods** for higher quality control.

Way forward

HOUSE

=

Engineering Theory

+

Material

+

Construction workers' skill

Improvement through reconstruction work

Appearance of structure parts (column, beam...)

Standardize of material

Improvement of const. Workers' skill & knowledge

- **Yogyakarta is a special case** – post-disaster area with reconstruction assistance for housing quality control.
- In **general case**, more **fundamental difficulties** will be found (No drawing, no financial assistance, no staff to check the quality).
- Need to develop **workers-friendly construction methods**.
- Consider the **balance** between **community's needs** (Originality) and **control convenience** (Prototype).